Quality Requirment

SI#	Description
1	Supplier shall submit their Quality Plan at bidding stage
2	Supplier shall submit their Quality Manpower and instrument list they
	used along with their calibration.
3	Supplier shall submit their standard QAP for SP review.
4	Supplier shall submit Type Test Report (in case of electrical) at the time
	of offering the item
5	Supplier shall submit project specific QAP/ITP after getting order
6	Supplier shall submit their WPS-PQR if weding is involved
7	All welding shall be done by qualified welders only and certificates of
	welders shall be submitted to SP for review.
8	Supplier shall perform all tests applicable to the item such as NDTs, leak
	test, heat treatment, check test at lab etc as per approved ITP/ Project
	Spec/ Drawing/ codes and standard.
9	Supplier shall perform all necessary electrical tests as applicable for
	electrical equipment
10	Inspection shall be planned and raise call 15 days advance advance to
	the actual inspection date.
11	Supplier shall raise online inspection call in SP DMS system
12	Supplier shall send the all internal inspection report and photographs of
	ready item 2 days prior to actual date of inspection.
13	In case of non readiness of item, Supplier shall intimate 2 days prior to
	the inspection date.
14	In case Inspector identify non readiness of item during inspection, cost of
	inspection (trip cost + inspection hrs) will be back charged to Supplier.
15	Supplier shall extend all necessary co operation to the inspector as
	necessary to inspect the item
16	Supplier to prepare all Inspecton and test report, MOM of the Inspection
	visit.
17	Signed off inspection, test report, MOM by all concerned parties shall be
	submitted by Supplier